


Consumption Meter

Compatible model:


AGF-AE-D

0 System Scheme Diagram



1 Mount the meter

The Meter should be mounted in a Power Distribution Box. Mount the meter on a 35mm DIN rail.



2 Install CTs

! TURN OFF AC POWER BEFORE OPERATION

i The current transformer is packed together with the meter


2.1 Install the CTs around the conductor to be measured. Split-core CTs can be opened for 3 installation around a conductor.

2.2 Arrow on the CTs should be the direction of current flow.

3 Wire the meter

i Clamp the CT connect to L1 CT around the wire connect to ØL1

i Clamp the CT connect to L2 CT around the wire connect to ØL2



3 Connect to Datalogger

